ELO Touch Driver Installation Guide

Version: V4.6.3 Update: 20090922

Trademarks

Some of the product names mentioned herein are used for identification purposes only and may be trademarks and/or registered trademarks of their respective owners.

Revision History:

Version	Date	Description
V4.6.3	Aug, 2009	release

Remark:

The below installation procedure is based on the version v4.6.3 and using Windows XP as an example, the installation procedure might slightly differ depending on the OS installed.

Driver Installation Procedure

Insert the Driver CD into your CD driver which is prior connected to the system then follow the installation instructions in the Setup Wizard. Detail instruction as below:

- 1. You can find the driver menu in the attached driver CD, please click the <Windows> in the <Touch> section. The procedure might slightly differ depending on the OS installed.
- 2. Click the <Windows> to run auto detective program for touch type installed or select the touch type directly to start the setup.

Model name Notherboard)	Function	os	Note
	Chipset	Windows	Installation Guide
	Intel SATA AHCI	Windows driver	Viser manual
		Min2K XP	Electalization Quide
		111121X,70	IEGD driver
VGA	VGA	Win2K, XP	Use for CRT output only
		Vista	
		Linux	
	Audio	Win2K, XP, 2003	Installation Guide
		Vista	
•	Realter HD Codec	Linux	-
		Dual Cara CBU	
	Windows XP update	Chinest	
- 1	Touch Screen auto detect / install program. Use for:		
	ELO POS Touch POS Touch-HID POS Touch+	Windows	Read Me
		DOS	
	Touch Screen		v463
		Windows	Installation Guide
	ELO Touch	WindowsWipha	v481 (alpha driver)
		Linux	
	Touch Screen	DUS	
	and an application of the second s	Windows	
	POSTouch	windows	Installation Guide
		Linux	
	PCI-E 1000Mb LAN	DOS	
		Win9X, ME, 2K, XP	Installation Guide
	Realtek RTL8111	Vista	
		Linux	
	Mini PCI-E IEEE802.11b/g/n Wireless LAN	Win2K, XP	
	200-000	Vista	
	• WS32L	WinXP 64bit	
BIOS flash utility	• • • • • • • • • • • • • • • • • • • •	Vista 64bit	
	and the second	DOS	1
	BIOS flash utility	Windows	
	Hardware Monitor	Windows	1
		DOS	With C language source code
	Watch Dog Timer (WDT) demo tool	Windows	With VB language source code
		Programming guide	
	Cash Drawer controller test utility	DOS	With C language source code
	(use I/O port 0x48C)	Windows	
	Finger Print Module	SDK for Windows and Linux	
	• U4500	Demo and Test program (Windows)	Installation and User Guide
	Magnetic Card Reader		
	S64 series	Windows	Utility
	Magnetic Card Reader		
	IDMB series	<u>Windows</u>	Utility

Driver list

3. To click <Install Touch Driver> to detect the touch type being installed on the system.



4. After detect the touch type, press <Install Touch Driver> again.



5. Click <OK> to run WinZip Self-Extractor for ELO touch driver version 4.6.3.



6. Click <Unzip> to extract the driver files to the specified folder.



7. Click <OK>.



8. Click <Next>.



9. Select <Install Serial Touchscreen Drivers> and click <Next>.



10. Click <Yes> to accept the License Agreement



11. Examining serial ports on the computer...



12. Check the box Auto-detect Elo devices and click <Next>



13. The computer is searching for a connected to Elo Touchscreen.



14. Touchscreen found on <COM5>. Click <Next>.



15. Click <Next> to complete the driver installation.



16. Driver is installing...

Elo TouchSystems Setup (Version 4.6.3)		
Instaling Elo Touchscreen divers and components		

17. The driver installation and setup are now complete. Click <Finish> to start the touchscreen calibration.

Elo TouchSystems Setup (Version 4.6.3)		
E TOUCHSYSTEMS	Setup Complete Setup has finished installing the Elo touchscreen drivers and components. You can choose to calibrate your Elo Touchscreen monitors after setup finishes.	
in and the second	✓ Calibrate Elo Touchscreen monitors. ✓ View Readme. Click Finish to exit Setup.	
	K Back	

18. Follow the instructions on the screen to calibrate the Touchscreen.



19. Verify that the touchscreen is working correctly by moving your finger on the screen. The mouse cursor should follow your finger. Finally, touch the green checkmark to save the calibration settings and exit the program.

